













UNIFLEX hose cutting machines have been a synonym for the highest precision and robustness for many decades. The solid and compact tools distinguish themselves by their safe and high-quality cutting function. A distinct property is the positioning of the extraordinarily sharp cutting blades close to the powerful motors. This significantly reduces vibration – which is one of the reasons for extreme durability and low maintenance costs.







The DC machines are ideal for mobile use.



	(Ellister)	E11 2	~ <u>=81</u>			
Technical Data	EM 1	EM 1 S	EM 1 SB	EM 3	EM 3 Ecoline	EM 3 DC
Production 4-spiral	-	-	-	3/4"	-	-
Workshop 4/6-spiral	-	1"	1"	11/4"	1"	11⁄4"
4-spiral	5/8"	11/4"	11/4"	11/4"	11/4"	11/4"
Industrial	11/4"	11/4"	11/4"	2"	11/4"	2"
Max. outside (mm)	Ø 45	Ø 52	Ø 52	Ø 80	Ø 52	Ø 60
Noise level	90 dBA	90 dBA	90 dBA	80 dBA	95 dBA	93 dBA
Brake motor	-	_	-	✓	-	-
Suction connection (mm)	-	-	Ø 30	Ø 80	Ø 40	Ø 40
Drive	1.2 kW 1~VAC	1.2 kW 1~VAC	Battery	3 kW 1~VAC	1.8 kW 1~VAC	12 V/24 V 2.0/3.2 kW
Cutting blade (mm)	TM 190x2.0x30 TM 190x2.0x15,875	TM C 190x2x30	TM C 160x2.5x20	TM 275x3x30	TM G 200x1.6x25.4	TM 250x2x40Z
L x W x H (mm)	300 x 340 x 310	300 x 340 x 310	400 x 300 x 415	540 x 440 x 300	400 x 510 x 540	550 x 365 x 410
Weight (kg)	8	8	7,5	50	20	29
Accessories						
TU Table	1	✓	1	1	✓	1
Suction device *	_	_	✓	✓	✓	✓
UVC 25 Adapter	-	-	520.7010	520.7014	520.7010	520.7010
UVC 50 Adapter	_	_	518.7010	518.7014	518.7010	518.7010
Hose measuring tool UMS 4	-	-	-	✓	1	-
Foot for UMS 4 (840 mm hight)	_	-	-	✓	✓	-
Hose guide 2,000 mm (UHG 14)	-	-	-	1	1	_

^{*} Adapter needed.

Suction & filter device page 68 / Options and accessories page 70

Description



Tested high-quality cutting blade, secured with a metal sheet.



Guide pins ensure straight cuts.



Blades

TM = plain


TM G = slotted

TM C = coated



High-quality cutting blades: TM C, TM G und TM.

Cutting blades



TM C
Lasts 7 times longer, cuts twice as fast, generates less smoke, less debris in the hose and less heat.
Reduces the risk of separation of the rubber from the wire.